


Methods and Results

All samples were taken with a Narda 06 E-9 monitor which was calibrated by the OSHA Cincinnati Technical Center on May 5, 2004. The diagrams below illustrate the levels that were detected during the survey. Those results in red indicate an overexposure to FCC standards.

Indoor

These samples were taken inside the lookout on the top level. No overexposures were detected inside the lookout.



Outdoor

